

Queue Number	2850015	Transaction Date	09 Oct 2026, 16:37:22
Site Name	840 - Emirates Auctions	Transaction Number	26344223 (CC10013) (CC10025)



Vehicle Details

Chassis Number	WAUY2BFD8F*****
Specification	GCC Specification
Make	Audi
Model	A8
Model Year	2015
Color	White
Mileage	240929 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		
01.A Fenders	FRONT LEFT SIDE PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR FULLY COVERED	الارضية
01.E Bonnet	PORTION DENTES , SHOCK NOT WORKING	غطاء المحرك
01.F Vehicle Color	WHITE / BLACK	لون المركبة
02 Chassis Condition		
02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		
03.A Engine Visual Condition	MINOR OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
04.A Seat Condition	BACK COVER DAMAGED	حالة المقاعد
05 Transmission Condition		
05.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES CRACK	ازرع
07.B Other	SUSPENSION PARTS REFITTED	اخرى
08 Interior Condition		الحالة الداخلية
08.A Other	REAR CONSOLE BOX COVER DAMAGED / INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Roof Ceiling	PORTION LOOSE	بطانه السقف
08.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
08.E Sunroof	CURTAIN NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae