



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Jan 2023, 15:44:24
Transaction Number	44056089 (CC10006)	Queue Number	657729



Chassis Number	JHMCP26358C410758
Engine Number	
Vehicle Class	Car
Manufacturer	Honda
Model	Accord
Model Year	2008
Color	Silver
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Floor	PORTION DENT .UNDERFLOOR RUSTPROOF COATED.	الارضية
01.B Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
01.C Paint	BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES ,PORTION FADED.	الصبغ
01.D Bumper	MISALIGN ,PORTION SCRATCHES .	دعامية
02 Lights		الاضاءة
02.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
03 Transmission Condition		الجير
03.A Road Test	NOT CHECKED .	فحص علي الطريق
03.B Visual Gear Box Condition	NOT CHECKED OILL EAK ,	حالة الجير النظري
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2016 EXPIRED CRACKED .	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2016/2019 EXPIRED CRACKED .	الاطار الامامي
05 Chassis Condition		الشاصي

DEFECT	REMARKS	
05.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
06 Interior Condition		الحاله الداخليه
06.A Other	GEAR KNOB PORTION FADED.	اخرى
06.B Odometer reading	NOT CHECKED .	قراءة عداد المسافات
06.C Roof Ceiling	LOOSE,	بطانه السقف
06.D AC Condition	NOT CHECKED .	المكيف
06.E Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
06.F Mirror	LEFT SIDE COVER BROKEN,	المرايا
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING . OIL LEAK.	حالة المحرك النظرى
08 Steering Condition		المقود
08.A Steering Box	OIL LEAK.	جهاز المقود
08.B Axle	BOOT CUT .	اكسلات
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CRACKED.	ازرع
09.B Shock Absorber	LEAK ,WEAK .	ممتص الصدمات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.