CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906275
Transaction Date	24 Oct 2026, 11:35:33
Site Name	840 - Emirates Auctions
Transaction Number	93877829 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KMHRB8A35P*******
Specification	Imported
Make	Hyundai
Model	Venue
Model Year	2023
Color	Black
Mileage	60700 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT RIGHT SIDE & REAR BOTH SIDE REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MIOR DNETS SCRATCHES .	الصبغ
01.C Doors	RIGHT SIDE BOTH DOORS REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED ,PORTION DENT .	الارضية
01.F Bumper	MINOR SCRATCHES.,	دعامية
01.G Windshield	REEAR WINDSHIELD CHANGED	زجاج
01.H Bonnet	REPAIRED REPAINTED	غطاء المحرك
01.I Trunk	REPAIRED REPAINTED	صندوق
01.J Sign of front accident	FRONT RIGHT SIDE FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident	RIGHT SIDE QUARTER PANEL WHEEL ARCH REPAIRED DENT .	وجود مؤشر لحادث في الجانب
01.L Sign of back accident	BACK PANEL REPAIRED DENT .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,EMPTY FUEL , ALL SYSTEM NOT CHECKED ,OIL LEAK ,COMPONENT PARTS GETTING RUSTY.	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,COMPONENT PARTS GETTING RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022 CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 CRACKED.	الاطار الخلفي
05.C Rims Condition	MINOR DETNS SCRATCHES .	حالة الجنوط
06 Brake Condition		الفرامل
06.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	WEAK,	ممتص الصدمات
07.B Arms	BUSHES DRY CRACKED.	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF WATER FLOODED	اخري
08.B AC Condition	NOT CHECKED/.	المكيف
08.C Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae