CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2986245
Transaction Date	13 Nov 2026, 16:51:27
Site Name	840 - Emirates Auctions
Transaction Number	98086838 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8AY25Y1B*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2011
Color	Beige
Mileage	125376 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED,GETTING RUSTY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK RUST PROOFED	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Windshield	PORTION CRACK	زجاج
01.F Roof	REPAINTED PORTION REPAIRED	السقف
01.G Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Trunk	PORTION REPAIRED REPAINTED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUST PROOFED PORTION GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	MINOR WHITE	دخان
03.B Other	ELECTRIC WIREING WORN OUT UNSAFE	اخري
03.C Engine Visual Condition	OIL WET , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	MIDDLE SEAT LEFT SIDE FOLDING HANDLE NOT WORKING	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE INNER CHROME CRACK PORTION LEAK	الاضاءة الرئيسية
07.B Fog light	NOT WORKING FADED	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخري
10.B AC Condition	LOW COOLING	المكيف
10.C Dash Board	PORTION CRACK MELTED	لوحة القياده
10.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.E Odometer reading	CLUSTER DISPLAY PORTION FADED	قراءة عداد المسافات
10.F Door Panel	FRONT LEFT SIDE LEATHER PORTION CRACKED	لوحة بطانة الباب
10.G Gear Shifting Lever	KNOB WORN OUT SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.