

TEST CERTIFICATE

Site Number
Transaction Number

05.A Visual Gear Box

06 Tires and Rims Condition

05.B Road Test

Condition

840-Emirates Auctions 26442487 (CC10006) Transaction Date

05 May 2022, 16:08:04

Queue Number 312309

Chassis Number

SALLAAAD4DA699072

Engine Number

Vehicle Class Car

Manufacturer Land Rover

Model

LR4

Model Year

2013

Color

Brown

Mileage

105058 Km

Fuel Type

Petrol

No. Of Cylinders

0

Specification

GCC Specification

حالة الجير النظرى

فحص علي الطريق

الاطارات

DEFECT REMARKS

O1 Body		جسم المركبة
01.A Doors	RIGHT SIDE BOTH REPAIRED, REPAINTED	أبواب
01.B Pillars	RIGHT SIDE DOOR PILLAR, ROCKER PANEL REPAIRED	القوائم
01.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
02 Suspension System		ممتص الصدمات
02.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
03 Chassis Condition		الشاصي
03.A Chassis	RIGHT MIDDLE CHASSIS REPAIRED, STILL MINOR BEND	الشاسيه
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودات
05 Transmission Condition		الجير

MINOR OIL LEAK

NOT CHECK

DEFECT	REMARKS	
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Engine Condition		المحرك
07.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
08 Interior Condition		الحاله الداخليه
08.A AC Condition	NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Possession Certificate: 6644939397 Chassis No: SALLAAAD4DA699072 Vehicle Make: **LAND ROVER** Vehicle Model: LR4 Vehicle Class: Light Vehicle **Body Type: STATION** Fuel: Benzene Color: Brown **Drive Direction:** Dimensions: (H x W x L) **Current Odometer:** 105063 Kms Previous Odometer Reading: 310365 Kms. Origin: Model Year: **Great Britain** 2013 Gear Type: Automatic Engine Size: 5000 CC Engine No: 1310072215... **Horse Power:** Axles No: Cylinders: 8 No Of Doors: 5 No Of Seats: G. V. W. : Empty Weight: 1600 Kgs. 2000 Kgs.

Certificate Number: 5-TAS-2022-16710647 Inspection Date: 08-05-2022 **Certificate Print Date:** 08-05-2022 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 16 min 34 sec Appointment Ref Number: --Start Time: 14:25 End Time: 14:42 Token No.: 272 Lane: 02 Attempt: 1 Prints No: 1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)



108969 KM

Distance per

year





18166 AED Fuel cost per year



26.8 ton
Carbon footprint
per year

Parameter Readings

Service brake imbalance on front axle 5 %

Service brake imbalance on rear axle 4 %

Parking brake imbalance between LHS and RHS 0%

Vehicle on Petrol CO Reading 0.48 %

Vehicle on Petrol HC Reading 189 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks: engine minor oil leak



Payment Details

Inspection Performed by
32858
59460

Parking Slot No
-Registration Test

Payment Method
Cash
16710647
16710647
Attempt
Attempt
Registration Test
1 Farsaction Number
16710647
Attempt
Attempt
Received by
Hussain Basha Akeel

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لفير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
 30. يوم من تاريخ الفحص



purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.