CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2277647
Transaction Date	30 Mar 2026, 10:20:37
Site Name	840 - Emirates Auctions
Transaction Number	62552695 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WDD2221761*******
Specification	Imported
Make	Mercedes
Model	S 600
Model Year	2018
Color	Black
Mileage	123844 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES .	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED,NEED TO REMOVE UNDER & FENDER COVER FOR PROPER INSPECTION,CHECKED VISIBLE AREA ONLY	الارضية
01.F Windshield	REAR CURTAIN LOOSE	زجاج
01.G Roof	ROOF RAIL REPAINTED	السقف
01.H Bonnet	REFITTED	غطاء المحرك
01.I Trunk	REPAINTED	صندوق
01.J Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY ,NOT VISIBLE PROPERLY ,CHECKED ONLY VISIBLE AREA/OK/.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK,SHAKING,PARTS REFITTED	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	GET JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	AIR SUSPENSION NOT WORKING PROPERLY.	ممتص الصدمات
09 Interior Condition		الحاله الداخليه
09.A AC Condition	NOT COOLING	المكيف
09.B Power Window Switch And Glass	MAIN SWITCH FRONT LEFT SIDE BUTTON MISSING	مفتاح النافذه و الزجاج
09.C Dash Board	LEATHER LOOSE	لوحة القياده
09.D Door Panel	WORN OUT,TRUNK SWITCH LOOSE	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Sunroof	CURTAIN NOT WORKING PROPERLY	فتحت سقف
09.G Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae