CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2922685
Transaction Date	29 Oct 2026, 16:07:23
Site Name	840 - Emirates Auctions
Transaction Number	41488776 (CC10009) (CC10025)



Vehicle Details

Chassis Number	JN8AY25Y4C*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2012
Color	Gold
Mileage	433783 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS CHASSIS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY THICK RUST PROOFED, MUDDY DIRTY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Windshield	FRONT SPOT CRACK	زجاج
01.H Roof	ROOF RAIL PARTS COVER MISSING	السقف
01.I Bonnet	REPAINTED , SHOCK NOT WORKING	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED, MUDDY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MUDDY ,	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Other	REAR CUP HOLDER COVER DAMAGED , INTERIOR PARTS GETTING RUSTY	اخري
09.B Mirror	CENTER MIRROR PORTION LOOSE , RIGHT SIDE FOLDING NOT WORKING LOOSE	المرايا
09.C AC Condition	OK	المكيف
09.D Dash Board	PORTION CRACK MELTED	لوحة القياده
09.E Door Panel	WORN OUT PORTION CRACK	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae