



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Nov 2021, 18:03:12
Transaction Number	63763667 (CC10006)	Queue Number	312309



Chassis Number	JN8AY2NY9F9119195
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2015
Color	--
Mileage	263221 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
01.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
02 Seats Condition		المقاعد
02.A Seat Belt	OK	حزام الأمان
02.B Seat Condition	FRONT LEFT SIDE SEAT COVER DAMAGED	حالة المقاعد
03 Wipers and Arms		المساحات
03.A Wiper Arm &Blade	WIPERS BLADE WORN OUT	ازرع المساحات والشفرات
04 Interior Condition		الحاله الداخليه
04.A Mirror	OK & RIGHT SIDE LIGHT COVER CRACKED	المرايا
04.B AC Condition	OK	المكيف
04.C Roof Light	OK	أنارة السقف
04.D Power Window Switch	OK	مفتاح النافذه
04.E Audio	OK	صوتيات
04.F Dash Board	OK	لوحة القيادة

DEFECT	REMARKS	
04.G Sun Visor	OK	حاجب الشمس
04.H Sunroof	OK	فتحت سقف
05 Body		جسم المركبة
05.A Fenders	PORTION REPAIRED, REPAINTED	مدكار
05.B Doors	PORTION REPAIRED, REPAINTED	أبواب
05.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
05.D Bumper	REPAINTED	دعامية
05.E Roof	ROOF , ROOF RAIL PORTION REPAIRED & REPAINTED	السقف
05.F Floor	UNDER FLOOR RUST PROOFED	الارضية
06 Lights		الاضاءة
06.A Head Light	OK	الاضاءة الرئيسية
07 Steering Condition		المقود
07.A Axel	FRONT RIGHT SIDE BOOT CUT & LEAK	اكسلات
08 Suspension System		ممتص الصدمات
08.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
08.B Shock Absorber	REAR BOTH SIDE LEAKING	ممتص الصدمات
09 Chassis Condition		الشاسي
09.A Chassis	OK	الشاسيه
10 Engine Condition		المحرك
10.A Engine Condition	OK	حالة المحرك
11 Transmission Condition		الجير
11.A Road Test	NOT CHECK	فحص علي الطريق
11.B Gear Box	OK	الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.