CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3001935
Transaction Date	17 Nov 2026, 14:28:43
Site Name	840 - Emirates Auctions
Transaction Number	62280216 (CC10021) (CC10021)



Vehicle Details

Chassis Number	JN6DD23S59*******
Specification	GCC Specification
Make	Nissan
Model	Pickup
Model Year	2009
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED PORTON RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER BODY PARTS PORTION DENT,MUDDY	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED . SCRATCHES .	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED,RUSTY WEAK	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL , QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUSTY HOLE WEAK BULGED,REAR RIGHT SIDE DAMAGED,	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		**ممتص الصدمات**
08.A Arms	LOWER ARM BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		**الحاله الداخليه**
09.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Door Panel	WORN OUT	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae