

Queue Number	2793211	Transaction Date	25 Sep 2026, 16:23:33
Site Name	840 - Emirates Auctions	Transaction Number	93391507 (CC10010) (CC10011)



Vehicle Details

Chassis Number	WBAHS7100H*****
Specification	GCC Specification
Make	BMW
Model	X1
Model Year	2017
Color	White
Mileage	95234 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REAR RIGHT SIDE,FRONT BOTH REPAINTED PORTION REPAINTED REFITTED,REAR LEFT PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAINTED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPE NSION PARTS GETTING RUSTY .	صدأ
01.E Floor	UNDER FLOOR COVERED ,CHECKED ONLY VISIBLE AREA .	الارضية
01.F Bumper	MISALIGN SCRATCHES,MODIFIED	دعامية
01.G Bonnet	REPAINTED REPAINTED,REFITTED	غطاء المحرك
01.H Trunk	REPAINTED REPAINTED,SWITCH MELTED	صندوق
01.I Sign of front accident	FRONT ASSEMBLY REFITTED ,BULKHEAD ,RADIATOR SUPPORT LOWER SUPPORT BRACKET REPAINTED	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BUMPER FRAME CRACK DENT ,BACK PANEL REPAINTED.	وجود مؤشر لحادث في الخلف

02 Chassis Condition الشاسي

02.A Chassis	CHECKED VISIBLE AREA /OK.	الشاسيه
--------------	---------------------------	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	REFITTED ,OIL LEAK ,COPONENT PARTS GETTING RUSTY. ABNORMAL NOISY.	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED , GET JERKING.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Interior Condition		الحالة الداخلية
06.A Other	CENTER CONSOLE BOX COVER DAMAGED	اخرى
06.B AC Condition	OK,REAR GRILL PANEL LOOSE	المكيف
06.C Roof Ceiling	PORTION MINOR LOOSE	بطانة السقف
06.D Door Panel	LEATHER PORTION LOOSE	لوحة بطانة الباب
06.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
06.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
06.G Engine Start Button	GETTING WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae