



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|----------------|
| Site Number | : 756-TASJEEL SHARJAH | Plate Code | : O |
| Transaction Number | : 17921568 | Plate Category | : PRIVATE |
| Transaction Date | : 19 AUG 2019 12:21:28 | Plate Number | : 21949 |
| Queue Number | : 93883 | Import Doc. Ref. | : |
| Chassis Number | : 1HGCR2637DA613220 | Manufacturer/Model | : HONDA/ACCORD |
| Engine Number | : | Model Year | : 2013 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : RED |
| Service / Indicator | : DSC AUCTION | Mileage | : 102082 |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|--------|--|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| 17 Shock Absorbers Test | | فحص مخمد الصدمات |
| 17.01 - Shock Absorber Test | Passed | فحص مخمد الصدمات |
| VISUAL TEST: | | |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.04 - Rear Left And Right Hand Tires | | الاطارات الخلفية |
| | | ALL TIRE MAJOR CRACK |
| 05 Body | | الهيكل |
| 05.02 - Paint | | BODY MINOR SCRATCHES & DENT |
| 05.03 - Doors | | REAR LHS DOOR REPD |
| 05.04 - Fenders | | REAR LHS FENDER REPD |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | OK | النشاصي جيد |
| 09.09 - Engine And Gear Box Performance Ok | OK | فحص حالة الماكينة والجير |
| 09.25 - Body Repainted | | LHS BOTH DOOR,RR LHS Q/PANEL PORTION RE-PAINTED |
| | | أثر صبغ في المركبة |

The Test Certificate Shows the test Result at the time of inspection only.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط