



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>14 Aug 2022, 11:26:02</b>
Transaction Number	<b>54467665 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>KMHL241BOLA098312</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Hyundai</b>
Model	<b>Sonata</b>
Model Year	<b>2020</b>
Color	<b>Silver</b>
Mileage	<b>41555 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظرى
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER FLOOR FULLY COVERED CHECKED VISIBLE AREA	الارضية
03.B Paint	BODY MINOR DENT SCRATCHES	الصبغ
03.C Bumper	FRONT BUMPER MISS ALIGNED, UNDER COVER DAMAGED.	دعامية
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
<b>05 Chassis Condition</b>		<b>الشاصي</b>
05.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA OK	الشاسيه
<b>06 Engine Condition</b>		<b>المحرك</b>

## DEFECT

## REMARKS

06.A Visual Engine Condition

OK

حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.