



### Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:	
Transaction Number	: 22391519	Plate Category	:	
Transaction Date	: 18 NOV 2020 15:57:44	Plate Number	:	
Queue Number	: 252873	Import Doc. Ref.	:	39303 EA
Chassis Number	: RKLBV42E6D4639303	Manufacturer/Model	:	TOYOTA/COROLLA
Engine Number	:	Model Year	:	2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	:	SILVER
Service / Indicator	: DSC AUCTION	Mileage	:	124000

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
05 Body		الهيكل
05.02 - Paint		الصبغ
05.05 - Bumpers		الدعامية
		B/S BUMPER & B/FAME REPD
09 Auction		الفحص الكامل
09.06 - Chassis Ok		الشاصي جيد
09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صبغ في المركبة
		FULL BODY PORTION REPAINTED
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية		