



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Sep 2022, 14:28:11
Transaction Number	64818845 (CC10006)	Queue Number	312309



Chassis Number	5TFDZ5BN1KX044709
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Tacoma
Model Year	2019
Color	White
Mileage	44730 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Roof Ceiling	PORTION LOOSE	بطانه السقف
01.C Air Bag	DAMAGED & MISSING	وسائد هوائية
01.D Dash Board	PORTION CRACK.	لوحة القيادة
02 Lights		الاضاءة
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03 Body		جسم المركبة
03.A Fenders	REFITTED	مدكار
03.B Bonnet	REFITTED ,REPAIRED ,REPAINTED.	غطاء المحرك
03.C Pillars	LEFT SIDE DOOR PILLAR ,ROOF & ROOF RAIL REPAIRED.	القوائم
03.D Sign of side accident		وجود مؤشر لحادث في الجانب
03.E Paint	BODY TOTALY REPAINTED REPAIRED , MINOR DENTS	الصبغ
03.F Doors	LEFT SIDE BOTH REFITTED	أبواب
03.G Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY.	صدأ
03.H Sign of front accident		وجود مؤشر لحادث في المقدمة
03.I Bumper	FRONT BUMPER FRAME ,BULKHEAD ,RADIATOR SUPPORT	دعامية

DEFECT	REMARKS	
	,CROSS MEMBER FENDER FRAME ,APRON REPAIRED.	
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	OIL WET	حالة الجير النظرى
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL WET	حالة المحرك النظرى
07 Chassis Condition		الشاسي
07.A Chassis	REART LEFT CHASSIS LOWER DENT .CHASSIS FRAME GETTING RUSTY.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	5TFDZ5BN1KX044709
Vehicle Make :	TOYOTA
Vehicle Model :	TACOMA
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	44731 Kms.
Origin : United States	Model Year : 2019
Gear Type : Automatic	Engine Size : 2500 CC
Engine No : NIL	Horse 173
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2700 Kgs.	Empty 2216 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17693535		
Inspection Date :	22-09-2022		
Certificate Print Date :	22-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	17 min 11 sec		
Appointment Ref Number :	--		
Start Time :	16:46	End Time :	17:03
Lane :	01	Token No. :	201
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

7455 KM	768 L	2558 AED	1.9 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	4 %	3 %	0 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2500	3600	

Inspection Remarks:

FRONT BULKHEAD/BUMPER/ FENDER&FRAME/BONNET/ FRONT LEFT SIDE PILLAR&RIGHR SIDE ROOF RAIL&ROOF REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	VTP Credit Account	17693535	AED 170 Collected on 22/09/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

