

Queue Number 2902261

Transaction Date 23 Oct 2026, 16:52:23

Site Name
840 - Emirates AuctionsTransaction Number
12719133 (CC10013) (CC10011)

Vehicle Details

Chassis Number	JN8AY2NY7D*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2013
Color	White
Mileage	140210 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مذكور
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED MISALIGN	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.I Trunk	REPAINTED REFITTED,REAR SWITCH DAMAGED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY OILY DIRTY PORTION GETTING RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	UPPER COVER PORTION DAMAGED	اخرى
03.B Engine Visual Condition	OIL LEAK ,REFITTED , PARTS GETTING RUSTY , MAJOR NOISY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT,ADJUSTMENT SWITCH PORTION DAMAGED,NOT WORKING PROPERLY	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Catalytic Converter	CUT REWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
06.C Four Wheel Drive	MINOR OIL LEAK	الدفع الرباعي
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Wipers and Arms		المساحات
08.A Other	BOTTLE CAP MISSING	اخرى
09 Lights		الاضاءة
09.A Tail Light	RIGHT SIDE PORTION DAMAGED	الضوء الخلفي
10 Suspension System		ممتص الصدمات
10.A Arms	ARM BUSHES DRY CRACK	ازرع
10.B Ball Joint	BOOT CUT	مفصل كروي
10.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
11 Interior Condition		الحالة الداخلية
11.A Other	COOL BOX EXTRA COVER,CUP HOLDER COVER NOT CLOSE,REAR CUP HOLDER DAMAGED,INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
11.B Mirror	LEFT SIDE LOOSE AUTO FOLDING NOT WORKING	المرآيا
11.C AC Condition	NO COOLING	المكيف
11.D Dash Board	PORTION DAMAGED MELTED WORN OUT	لوحة القيادة
11.E Door Panel	PORTION DAMAGED	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11.H Engine Start Button	FADED	زر تشغيل المحرك
12 Battery Condition		حالة البطارية
12.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae