

Queue Number 2887497

Transaction Date 20 Oct 2026, 11:26:49

Site Name
840 - Emirates AuctionsTransaction Number
87730749 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WA1CFCFP2F*****
Specification	GCC Specification
Make	Audi
Model	Q5
Model Year	2015
Color	Brown
Mileage	120153 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY CHECKED VISIBLE AREA ONLY	الارضية

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FULLY COVERED MUDDY CHECKED VISIBLE AREA OK	الشاسيه
--------------	---	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED TOP COVER CRACKED	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	RIGHT SIDE SEAT PORTION CRACKED , ADJUSTMENT ABNORMAL NOISE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

06 Tires and Rims Condition الاطارات

06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي

Condition	Remarks	الحالة
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING MESSAGE ON IN DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK	المكيف
10.C Roof Ceiling	REPLACED , PORTION LOOSE	بطانة السقف
10.D Sun Visor	RIGHT SIDE BRACKET DAMAGED	حاجب الشمس
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae