

Queue Number 2479280

Transaction Date 22 Jun 2026, 16:51:23

Site Name
840 - Emirates AuctionsTransaction Number
63708507 (CC10009) (CC10011)

Vehicle Details

Chassis Number	KNAPB8116B*****
Specification	GCC Specification
Make	Kia
Model	Sportage
Model Year	2011
Color	Silver
Mileage	130367 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED, EXCEPT ROOF, MINOR DENTS SCRATCHES, PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR MUDDY PORTION DENT, FRONT LEFT SIDE FIRE WALL REPAIRED	الارضية
01.E Bumper	MISALIGN, PART MISSING	دعامية
01.F Bonnet	RELEASE HANDLE LOOSE, REFITTED, MISALIGN	غطاء المحرك
01.G Pillars	A/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED	القوائم
01.H Trunk	INNER COVER SCRATCHES, LUGGAGE SHADE MISSING	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME LEFT SIDE WHEEL ARCH REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED LEFT SIDE CHASSIS REPAIRED, REAR RIGHT SIDE SKIRT DENT	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY MUDDY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	REAR HEAD REST MISSING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL WET REFITTED, JERKING GETTING RUSTY, DELAY SHIFTING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	TOOLS MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED,RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED	الضوء الخلفي
07.C Indicator & Hazard light	REAR BOTH SIDE FADED	الاشارات
07.D Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT, INNER PARTS RUSTY	اخرى
09.B Mirror	LEFT SIDE COVER PORTION CRACKED	المرآيا
09.C AC Condition	OK	المكيف
09.D Power Window Switch And Glass	REAR RIGHT SIDE NOT WORKING PROPERLY FROM MAIN SWITCH PANEL	مفتاح النافذه و الزجاج
09.E Audio	DISPLAY DAMAGED	صوتيات
09.F Dash Board	PORTION LOOSE WORN OUT	لوحة القيادة
09.G Odometer reading	NOT VISIBLE,DISPLAY PORTION FADED,TRIP SWITCH NOT WORKING	قراءة عداد المسافات
09.H Steering Wheel and control buttons	WORN OUT,HORN NOT WORKING,AIR BAG UNIT,STEERING MISALIGN	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	DUST COVER PORTION LOOSE,SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae