CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2986559
Transaction Date	13 Nov 2026, 16:51:38
Site Name	840 - Emirates Auctions
Transaction Number	15016981 (CC10013) (CC10011)



Vehicle Details

Chassis Number	1GTHK23U56*******
Specification	GCC Specification
Make	GMC
Model	Sierra
Model Year	2006
Color	Yellow
Mileage	69932 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES,PORTION FADED RUSTY,PAINT PORTION DAMAGED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUST PROOFED MOUNT RUBBER DRY CRACK	الارضية
01.D Windshield	SPOT CRACK	زجاج
01.E Bonnet	REFITTED	غطاء المحرك
01.F Trunk	REAR CABIN MODIFIED,PORTION DAMAGED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY THICK RUST PROOFED MUDDY DIRTY GETTING RUSTY	الشاسيه
02.B Chassis Number	DOOR POST STICKER FADED / CHECK GLOVE BOX STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Other	INNER COMPARTMENT ELECTRIC WIREING WORN OUT UNSAFE	اخري
03.B Engine Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY , OIL SWEATING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	REAR PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	FADED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Stabilizer Bar And Link Rod	BOOT DRY CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK	المكيف
09.C Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING PROPERLY NOISY	مفتاح النافذه و الزجاج
09.D Audio	NOT WORKING	صوتيات
09.E Dash Board	PORTION MODIFIED HOLE	لوحة القياده
09.F Roof Ceiling	PORTION LOOSE	بطانه السقف
09.G Door Panel	REAR LEFT SIDE LIGHT MISSING,RIGHT SIDE A/PILLAR COVER PORTION LOOSE FIX BY SCREW	لوحة بطانة الباب
09.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae