



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>23 Jan 2023, 14:25:46</b>
Transaction Number	<b>40609378 (CC10006)</b>	Queue Number	<b>660732</b>



Chassis Number	<b>4T1BG22K01U845922</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Camry</b>
Model Year	<b>2001</b>
Color	<b>White</b>
Mileage	<b>001 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT CHECKED .	المكيف
01.B Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
01.C Mirror	LEFT SIDE BROKEN .	المرايا
01.D Door Panel	LOOSE.	لوحة بطانة الباب
01.E Roof Ceiling	LOOSE	بطانه السقف
<b>02 Steering Condition</b>		<b>المقود</b>
02.A Steering Boot	BOOT CUT .	ربلة المقود
02.B Axle	BOOT CUT .	اكسلات
02.C Steering Box	OIL LEAK .	جهاز المقود
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2021 CRACKED .	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2021 CRACKED .	الاطار الامامي
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSHES CUT .	ازرع
04.B Ball Joint	BOOT CUT .	مفصل كروي

DEFECT	REMARKS	
04.C Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Bumper	MISALIGN ,DAMAGE .	دعامية
05.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
05.C Sign of back accident		وجود مؤشر لحادث في الخلف
05.D Floor	UNDER FLOOR DENT . BACK PANEL ,QUARTER PANEL ,COMPARTMENT REPAIRED,	الارضية
05.E Paint	BODY PORTION REPAIRED , REPAINTED & DENT ,SCRATCHES,PAINT FADED ,RUSTY .	الصبغ
05.F Sign of front accident		وجود مؤشر لحادث في المقدمة
05.G Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED .	اخرى
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	REFITTED OIL LEAK .	حالة الجير النظري
06.B Road Test	NOT CHECKED .	فحص علي الطريق
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED.	الاضاءة الرئيسية
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK ,REFITTED	حالة المحرك النظري
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.