



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>24 Jan 2023, 16:23:11</b>
Transaction Number	<b>54929632 (CC10010)</b>	Queue Number	<b>657741</b>



Chassis Number	<b>JM7GG32F661518135</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mazda</b>
Model	<b>6</b>
Model Year	<b>2006</b>
Color	<b>Black</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
01.B Tail Light	LEFT SIDE PORTION DAMAGED	الانارة
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	NOT CHECK,OIL LEAK	حالة الجير النظري
<b>03 Chassis Condition</b>		<b>الشاصي</b>
03.A Chassis	OK	الشاسيه
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Bumper	MISALIGN,PORTION DAMAGED	دعامية
04.B Floor	UNDER FLOOR RUST PROOFED,PORTION DENT	الارضية
04.C Bonnet	REFITTED	غطاء المحرك
04.D Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
04.E Windshield	FRONT CRACKED	زجاج
04.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2018 EXPIRED,CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018 EXPIRED,CRACKED	الاطار الخلفي
<b>06 Interior Condition</b>		<b>الحالة الداخليه</b>
06.A AC Condition	NOT CHECK	المكيف
06.B Odometer reading	NOT CHECK	قراءة عداد المسافات
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
07.B Axle	AXLE CASE LEAKING	اكسلات
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK ,OIL SUMP REPAIRED	حالة المحرك النظري
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	LOWER ARM BUSH CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.