



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>28 Sep 2022, 12:15:45</b>
Transaction Number	<b>19095709 (CC10009)</b>	Queue Number	<b>597294</b>



Chassis Number	<b>WBALM1101CE761811</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>Z4</b>
Model Year	<b>2012</b>
Color	<b>White</b>
Mileage	<b>221609 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
01.B Fenders	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
01.C Bumper	MISALIGN	دعامية
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.E Windshield	REAR CURTAIN PORTION DAMAGED	زجاج
01.F Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
02.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.C Road Test	NOT CHECK	فحص علي الطريق
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Arms	LOWER ARM BUSHES CRACKED	ازرع
03.B Ball Joint	BOOT CUT	مفصل كروي
03.C Other	STABLIZER LINK BOOT CUT	اخرى

DEFECT	REMARKS	
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
05.C Rims Condition	SCRATCHES	حالة الجنوط
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A AC Condition	OK	المكيف
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.