

TEST CERTIFICATE

Site Number Transaction Number

02 Steering Condition

04.A Roof

840-Emirates Auctions 93873622 (CC10009)

Transaction Date

04 Dec 2022, 17:15:08

Queue Number 635618

Chassis Number

JTGJX02P355000565

Engine Number

Vehicle Class

Manufacturer Toyota

Model

Car

Model Year

Hiace 2005

Color

White

Mileage

268944 Km

Fuel Type

Petrol

No. Of Cylinders

Specification

GCC Specification

المقود

لوحة القياده

السقف

REMARKS DEFECT

01 Tires and Rims Condition	الاطارات

01.A Front Tyre	BOTH SIDE 2018 CRACKED,	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 CRACKED,	الاطار الخلفي

02.A Tie Rod End **BOOT CUT** مؤخرة الرودات

03 Interior Condition	الحاله الداخليه

		•
03.A Other	CONSOLE BOX COVER MISSING	اخري
03.B Dash Board	PORTION DAMAGED	لوحة القياده

03.C AC Condition OK المكيف **REAR LOOSE**

03.D Roof Ceiling بطانه السقف

04 Body جسم المركبة **PORTION HOLE**

04.B Paint BODY PORTION REPAIRED, REPAINTED & MINOR DENT الصبغ ,SCRATCHES,PORTION RUSTY

04.C Sign of back accident وجود مؤشر لحادث في الخلف

04.D Bumper MISALIGN دعامية

04.E Other **BACK PANEL CROSS MEMBER REPAIRED** اخري

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظرى
05.C Gear Box Mount	MOUNT CRACK	كرسي الجير
06 Engine Condition		المحرك
06.A Mount	MOUNT CRACK	كرسي
06.B Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظرى
07 Suspension System		ممتص الصدمات
07.A Leaf Spring	BUSHES WORN OUT	
07.B Ball Joint	BOOT CUT	مفصل كروي
07.C Arms	LOWER ARM BUSHES CRACKED	ازرع
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
09 Chassis Condition		الشاصي
09.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.