CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934047
Transaction Date	02 Nov 2026, 15:47:48
Site Name	840 - Emirates Auctions
Transaction Number	90295788 (CC10008) (CC10008)



Vehicle Details

Chassis Number	KMHCT41B5F*******
Specification	GCC Specification
Make	Hyundai
Model	Accent
Model Year	2015
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR RIGHT SIDE PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT,SCRATCHES ,PORTION RUSTY,PORTION GETTING FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	PORTION DENT	الارضية
01.F Bumper	MISALIGN ,FIXED BY SCREW	دعامية
01.G Trunk	PORTION REPAINTED	صندوق
01.H Sign of side accident	REAR RIGHT SIDE QUATER PANEL REPAIRED	وجود مؤشر لحادث في الجانب
01.I Sign of back accident	BACK PANEL MINOR DENT	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,PARTS GETTING RUSTY,OIL WET ,REFITTED	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECK,PARTS GETTING RUSTY,OIL WET ,REFITTED	الحالة النظريه للجير

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED,LEFT SIDE CRACK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR RIGHT SIDE OIL LEAK	ممتص الصدمات
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	LEFT SIDE FUSE BOX COVER MISSING	لوحة القياده
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae