



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 20407791	Plate Category	:
Transaction Date	: 29 JUL 2020 08:57:09	Plate Number	:
Queue Number	: 201886	Import Doc. Ref.	: 002673 EA
Chassis Number	: LVAV2MWBXGJ002673	Manufacturer/Model	: FOTON/TUNLAND
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 57924

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
05 Body		الهيكل
05.02 - Paint		الصنع
05.05 - Bumpers		الدعامية
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.11 - Gear Box Oil Leaking		تهريب زيت الجير
		GEAR OIL LEAK

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسؤولة عن العيوب الخفية