



### Test Certificate

Site Number	: 756-TASJEEL SHARJAH	Plate Code	:
Transaction Number	: 18469644	Plate Category	:
Transaction Date	: 07 NOV 2019 09:04:47	Plate Number	:
Queue Number	: 115777	Import Doc. Ref.	: 219487 DXB
Chassis Number	: RKLBL9HE3F5219487	Manufacturer/Model	: TOYOTA/COROLLA
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION	Mileage	: 121591

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفرامل
13.04 - Brake Test	Passed		فحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
17 Shock Absorbers Test			فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed		فحص مخمد الصدمات
VISUAL TEST:			
01 Lights			الانوار
01.04 - Head Lights		B/S HEAD LIGHT LEG DAMAGED	الانوار الامامية
05 Body			الهيكل
05.02 - Paint		MINOR SCRATCHES & DENT	الصبغ
05.04 - Fenders		FRT FENDER REPAIRED	المدكار
05.05 - Bumpers		BUMPER REPAIRED	الدعامية
09 Auction			الفحص الكامل
09.06 - Chassis Ok	OK		الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK		فحص حالة الماكينة والجير
09.25 - Body Repainted		BODY PORTION REPAINTED	أثر صبغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.			
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط			