



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 May 2022, 17:24:18
Transaction Number	91855286 (CC10006)	Queue Number	312309



Chassis Number	KNAJP8146J7541317
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Soul
Model Year	2018
Color	White
Mileage	59170 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق
03 Tires and Rims Condition		الاطارات
03.A Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
03.B Rear Tyre	BOTH SIDE 2014/2017 EXPIRED & CRACKED	الاطار الخلفي
03.C Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
04 Body		جسم المركبة
04.A Doors	FRONT LEFT SIDE REPAINTED	أبواب
04.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHE	الصبغ
04.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
05 Chassis Condition		الشاصي

DEFECT	REMARKS	
05.A Chassis	OK	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.