



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **09 Mar 2023, 13:04:08**  
 Transaction Number **57680488 (CC10008)** Queue Number **685130**



Chassis Number **WBABD51090PK27894**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **BMW**  
 Model **330 CI**  
 Model Year **2004**  
 Color **--**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **Imported**

DEFECT	REMARKS	
<b>01 Engine Condition</b> <span style="float: right;">المحرك</span>		
01.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING	حالة المحرك النظري
<b>02 Interior Condition</b> <span style="float: right;">الحاله الداخليه</span>		
02.A Steering Wheel and control buttons	WORNOUT	عجلة القيادة وازرار التحكم
02.B Odometer reading	NOT CHECKED	قراءة عداد المسافات
02.C AC Condition	NOT CHECKED	المكيف
<b>03 Body</b> <span style="float: right;">جسم المركبة</span>		
03.A Vehicle Color	SILVER	لون المركبة
03.B Paint	PAINT NOT CHECKED,MINOR DENT SCRATCHES ON BODY ,PORTION FADED,PORTION RUSTY	الصبغ
03.C Floor	UNDER BODY PARTS,SUSPENSION ,FLOOR,CHASSIS NOT CHECKED	الارضية
03.D Other	VISUAL TEST ONLY	اخرى
<b>04 Chassis Condition</b> <span style="float: right;">الشاسي</span>		
04.A Chassis	NOT CHECKED	الشاسيه
04.B Chassis Number	VIN CHECKED ONLY ON FRONT RIGHT SIDE FENDER APRON	رقم القاعدة

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	CRACKED	الاطار الخلفي
05.B Front Tyre	CRACKED	الاطار الامامي
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Visual Gear Box Condition	NOT CHECKED	حالة الجير النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.