CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972553
Transaction Date	11 Nov 2026, 17:02:19
Site Name	840 - Emirates Auctions
Transaction Number	26416432 (CC10008) (CC10011)



Vehicle Details

Chassis Number	JN8AY25Y2A*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2010
Color	Blue
Mileage	132508 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES(BODY SHAPE CHANGE OLD TO NEW MODEL)	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS ,CHASSIS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Pillars	DOOR PILLARS ROCKER OUTER PANEL REPAIRED	القوائم
01.H Trunk	REFITTED SHOCK WEAK,REAR SWITCH MELTED,INNER COVER PART MISSING,COMPARTMENT COVER HANDLE DAMAGED	صندوق
01.I Door Handle &Lock	FRONT LEFT SIDE DOOR OUTER HANDLE LOCK COVER MISSING	مقابض الأبواب والأقفال
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK ,COMPONENTS REFITTED ,OIL PAN DRAIN NUT AREA WELDED REPAIRED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT SEATS MINOR LOOSE,MIDDLE NECK REST MISSING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK	الحالة النظريه للجير
05.B DIFFERENTIAL	MOUNT BUSHES CRACK	الدفرنشل
05.C Road Test	NOT CHECK	فحص علي الطريق
05.D Four Wheel Drive	NOT WORKING	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	SOME WARNING LIGHT HIIDEN ON DISPLAY	ضوء تحذير
07.B Fog light	NOT WORKING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود
10.B Steering Mount	BUSHES CRACK	كرسي المقود
10.C Steering Boot	BOOT CUT	ربلة المقود
10.D Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,INTERIOR MODIFIED PARTS REFITTED	اخري
11.B Mirror	LEFT SIDE ADJUSTMENT NOT WORKING PROPERLY,RIGHT SIDE NOT WORKING	المرايا
11.C Roof Light	PANEL MISALIGN,FRONT LEFT SIDE NOT WORKING	أنارة السقف
11.D Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING,FRONT RIGHT SIDE SWITCH PORTION DAMAGED	مفتاح النافذه و الزجاج
11.E Dash Board	PORTION WORN OUT LOOSE	لوحة القياده
11.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11.G Engine Start Button	WORN OUT,CHROME LOOSE	زر تشغيل المحرك
12 Battery Condition		حالة البطارية
12.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**