



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	03 Jul 2022, 15:46:33
Transaction Number	20309384 (CC10006)	Queue Number	312309



Chassis Number	WDDNG71X18A188643
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	S 500
Model Year	2008
Color	Black
Mileage	170061 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظري
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020 MINOR CRACKED	الاطار الامامي
03.B Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
03.C Rear Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الخلفي
04 Body		جسم المركبة
04.A Sign of side accident		وجود مؤشر لحادث في الجانب
04.B Floor	UNDER FLOOR FENDERS CHASSIS FULLY COVERED , CHECKED VISIBLE AREA	الارضية
04.C Other	BACK PANEL REAR RIGHT SIDE QUARTER PANEL REPAIRED	اخرى
04.D Trunk	TRUNK AUTO NOT WORKING PROPERLY	صندوق
04.E Fenders	FRONT FENDER REFITTED	مدكار

DEFECT	REMARKS	
04.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
05 Chassis Condition		الشاصي
05.A Other	FOR RECHECK REMOVE REAR RIGHT FENDER FLOOR COVER	اخرى
05.B Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER SCREEN MOVER COVER MISSING	اخرى
08.B AC Condition	OK	المكيف
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.