CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945018
Transaction Date	06 Nov 2026, 16:18:23
Site Name	840 - Emirates Auctions
Transaction Number	60842247 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTDEPRAEXL*******
Specification	Imported
Make	Toyota
Model	Corolla
Model Year	2020
Color	Blue
Mileage	152210 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR THICK RUST PROOFED , PORTION DENT	الارضية
01.E Bumper	MISALIGN, PORTION DAMAGE FIX BY SCREW	دعامية
01.F Bonnet	RELEASE HANDLE DAMAGE	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME , BULK HEAD , FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FULLY COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE CRACK	**الاطار الامامي**
06.B Rear Tyre	BOTH SIDE CRACK	**الاطار الخلفي**
06.C Rims Condition	MINOR DENT SCRATCHES	**حالة الجنوط**
07 Interior Condition		**الحاله الداخليه**
07.A Other	CENTER CONSOLE BOX PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	**اخري**
07.B AC Condition	OK	**المكيف**
07.C Dash Board	PORTION WORN OUT	**لوحة القياده**
07.D Roof Ceiling	PORTION WORN OUT	**بطانه السقف**
07.E Steering Wheel and control buttons	PORTION WORN OUT	**عجلة القيادة وازرار التحكم**
07.F Gear Shifting Lever	PORTION WORN OUT	**ذراع نقل السرعات**

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae