

TEST CERTIFICATE

Site Number Transaction Number

02.A Mirror

840-Emirates Auctions 98084850 (CC10008)

Transaction Date

08 Sep 2022, 12:26:53

Queue Number 312309

Chassis Number

1HGCT1271GA600133

Engine Number

Vehicle Class Car

Manufacturer Honda

Model **Accord**

2016 Model Year

Color Silver

Mileage 215090 Km

Fuel Type **Petrol**

No. Of Cylinders

Specification **GCC Specification**

REMARKS DEFECT

O1 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED	مدکار
01.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.C Bumper	BUMPER HAVE MINOR DENT SCRATCHES	دعامية

01.D Floor BOTH SIDE RUNNING BOARD DENT الارضية

01.E Bonnet PORTION REPAIRED, REPAINTED, REFITTED غطاء المحرك

02 Interior Condition الحاله الداخلية RIGHT SIDE COVER, LOOSE, GLASS DAMAGED, AUTO

FOLDING NOT WORKING & VIEW MIRROR LOOSE 02.B AC Condition OK

المكيف

03 Tires and Rims Condition الاطارات

03.A Rear Tyre **BOTH SIDE 2020 CRACKED** الاطار الخلفي 03.B Rims Condition RIMS HAVE MINOR DENT SCRATCHES حالة الجنوط 03.C Front Tyre **BOTH SIDE 2020 CRACKED** الاطار الامامى

04 Chassis Condition الشاصي

04.A Chassis FRONT RIGHT SIDE CHASSIS INNER MINOR DENT الشاسيه

المرايا

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظرى
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودات
07 Suspension System		ممتص الصدمات
07.A Ball Joint	BOOT CUT	مفصل كروي
07.B Arms	LOWER ARM BUSHES CUT	ازرع
O8 Lights		الاضاءة
08.A Head Light	LEFT SIDE LENS PORTION DAMAGED,BRACKET DAMAGED	الاضاءة الرئيسية
09 Engine Condition		المحرك
09.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.