

## **TEST CERTIFICATE**

Site Number Transaction Number **840-Emirates Auctions** 16493217 (CC10006)

Transaction Date

05 May 2022, 16:08:27

Oueue Number 312309

Chassis Number

JNKCV64E08M130208

**Engine Number** 

Vehicle Class

Car Infiniti

Model

Model Year

Manufacturer

G 37

2008

Color

Grey

Mileage

101724 Km

Fuel Type

**Petrol** 

No. Of Cylinders

Specification

**USA** Imported

REMARKS **DEFECT** 

01 Body جسم المركبة

**BODY TOTALY REPAINTED EXCEPT DOORS & PORTION** 

REPAIRED, DENT SCRATCHES

مدكار

الصبغ

01.B Fenders

01.A Paint

REPAINTED, REFITTED

01.C Bonnet

REPAINTED & SHOCK WEAK **REPAINTED & PORTION REPAIRED**  غطاء المحرك السقف

01.D Roof

FRONT FENDER FRAME, RADITOR SUPPORT, BUMPER

01.E Other

FRAME, BULK HEAD REPAIRED

اخري

01.F Sign of front accident

UNDER BODY PARTS GETTING RUSTY **REPAINTED** 

وجود مؤشر لحادث في المقدمة

01.G Rusty 01.H Trunk

صندوق

صدأ

**02 Seats Condition** 

المقاعد

02.A Seat Condition DAMAGED حالة المقاعد

**03 Steering Condition** 

المقود

03.A Steering Oil MINOR OIL LEAK

زيت المقود

03.B Tie Rod End **BOOT CUT** 

مؤخرة الرودات

**04 Suspension System** 

ممتص الصدمات

DEFECT	REMARKS	
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	ОК	حالة الجير النظرى
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK & GRAIL PORTION DAMAGED	المكيف
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
09 Chassis Condition		الشاصي
09.A Chassis	FRONT LEFT SIDE CHASSIS BEND	الشاسيه
10 Engine Condition		المحرك
10.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
  Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**









Plate Details:		Q 75820 Dubai Private				
Chassis No:	J	NKC	/64E08M130208			
Vehicle Make:		INFIN	NITI			
Vehicle Model:		37G				
Vehicle Class:		Light Vehicle				
Body Type:		Coupe				
Fuel:		Benzene				
Color:		Gray				
Drive Direction :						
Dimensions : (H	x W x L) -	x-	-x			
Current Odomet	er: 1	6371	2 Kms.			
<b>Origin:</b> Ja	pan		Model Year:	2008		
Gear Type: A	utomatic		Engine Size:	5600 CC		
Engine No: N	IL		Horse Power:	330		
Axles No: 2			Cylinders:	6		
No Of Doors: 2			No Of Seats:	4		
C 1/ 1//		_	<b>Empty Weight</b>	: 1600 Kas.		
G. V. W. :			Empty Weight	•		

Certificate Number: 5-TAS-2022-16720308 Inspection Date: 09-05-2022 Certificate Print Date : 09-05-2022 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 13 min 7 sec Appointment Ref Number: --Start Time: 10:59 End Time: 11:12 Lane: Token No.: 164 Attempt : Prints No: 1 1

### Carbon footprint



Thank you! You are environment protector

### Estimated Vehicle Consumption (Rate last 12 Months)



12803 KM

Distance per

year

1318 L Fuel consumed per year

2136 AED

Fuel cost per Carbon footprint vear per year



# **Parameter Readings**

Service brake imbalance on front axle

17 %

Service brake imbalance on rear axle 23 %

Parking brake imbalance between LHS and RHS 20 %

Vehicle on Petrol CO Reading 0%

## Vehicle on Petrol HC Reading 4 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5600	3700	

### **Inspection Remarks:**

FRONT LEFT SIDE FENDER, FRONT LEFT SIDE CHASSIS MIDDLE SLIGHTLY KINK, PASS AS PER OLD TRANSACTION ...///

# **Payment Details**

**Inspection Performed by Payment Method Transaction Number Service Fees** 59460 Cash 16720308 AED 170 Collected on 09/05/2022 Parking Slot No Service Name **Attempt** Received by Sittu Paloth Sreesan Paloth Registration Test

- 🐧 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.