



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Dec 2022, 14:09:40
Transaction Number	54262343 (CC10008)	Queue Number	641893



Chassis Number	WDCOG4JB8JV112871
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	GLC 300
Model Year	2018
Color	White
Mileage	64610 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	REFITTED	أبواب
01.B Pillars	DOOR PILLAR ROOF RAIL ,REINFORCEMENT REPAIRED	القوائم
01.C Floor	UNDER BODY FULLY COVERED&VISIBLE AREA CHECK ONLY& COVER DAMAGED	الارضية
01.D Sign of back accident		وجود مؤشر لحادث في الخلف
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
01.F Fenders	REFITTED	مدكار
01.G Roof	ROOF RAIL REPAIRED,REPAINTED	السقف
01.H Other	REAR BOTH SIDE QUATER PANEL WHEEL ARCH ,ROCKER PANEL ,BACK PANEL REPAIRED	اخرى
01.I Trunk	TRUNK NOT WORKING PROPERLY & REFITTED	صندوق
01.J Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES ON BODY	الصبغ
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
03 Interior Condition		الحاله الداخليه
03.A AC Condition	OK	المكيف
03.B Power Window Switch	REAR RIGHT SIDE NOT WORKING	مفتاح النافذه
03.C Sunroof	NOT WORKING PROPERLY & CURTAIN MISSING	فتحت سقف
03.D Roof Light	REAR RIGHT SIDE COVER MISSING & LEFT SIDE LOOSE	أنارة السقف
03.E Roof Ceiling	PORTION LOOSE	بطانه السقف
03.F Air Bag	DAMAGED & MISSING	وسائد هوائية
03.G Other	REAR RIGHT SIDE ROCKER PANEL COVER MISSING	اخرى
04 Engine Condition		المحرك
04.A Visual Engine Condition	OK	حالة المحرك النظرى
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	RIGHT SIDE 2021/LEFT 2016 EXPIRED ,CRACKED WORN OUT	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2020/2019, WORN OUT	الاطار الامامي
06 Chassis Condition		الشاسي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.