

Queue Number 2884776

Transaction Date 23 Oct 2026, 14:39:42

Site Name
840 - Emirates AuctionsTransaction Number
48314542 (CC10009) (CC10012)

Vehicle Details

Chassis Number	W1N4M4HBOP*****
Specification	Imported
Make	Mercedes
Model	GLB 250
Model Year	2023
Color	Black
Mileage	25218 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED PORTION REPAIRED , REFITTED , SKIRT WORN OUT	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED	الارضية
01.F Roof	LEFT SIDE ROOF RAIL PORTION FADED	السقف
01.G Pillars	LEFT SIDE A / B / PILLAR ROCKER PANEL REPAIRED	القوائم
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	OK	الشاسيه
02.B Chassis Number	REFITTED	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY MINOR SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	REAR RIGHT SIDE NOT WORKING	حالة المقاعد
---------------------	-----------------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2022 CRACK , RIGHT SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A AC Condition	OK	المكيف
08.B Door Panel	LEFT SIDE WORN OUT	لوحة بطانة الباب
08.C Air Bag	LEFT SIDE REFITTED	وسائد هوائية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae