CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2944998
Transaction Date	06 Nov 2026, 16:19:36
Site Name	840 - Emirates Auctions
Transaction Number	39691045 (CC10013) (CC10013)



Vehicle Details

Chassis Number	JM7GJ4S38G*******
Specification	GCC Specification
Make	Mazda
Model	6
Model Year	2016
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION CRACK	دعامية
01.E Trunk	NOT OPEN	صندوق
01.F Fuel Tank	DENT	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	FRO FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE COVER FOR RECHECK	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY PORTION WORN OUT	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	DENT	اخري

Condition	Remarks	الحالة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2022 DRY CRACK	الاطار الامامي
07.B Rear Tyre	2022 DRY CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK	ممتص الصدمات
10.B Arms	ALL BUSHES DRY CRACK	ازرع
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY	اخري
11.B AC Condition	NOT CHECKED	المكيف
11.C Dash Board	GETTING FADED PORTION WORN OUT	لوحة القياده
11.D Sun Visor	GETTING LOOSE	حاجب الشمس
11.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Engine Start Button	REMOTE SENSOR NOT DETECTED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae