



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 19 Jun 2022, 11:34:10 |
| Transaction Number | 87780640 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | JHMCP2636BC406564 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Honda |
| Model | Accord |
| Model Year | 2011 |
| Color | Silver |
| Mileage | 166156 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|------------------------|
| 01 Transmission Condition | | الجير |
| 01.A Road Test | NOT CHECKED | فحص علي الطريق |
| 01.B Visual Gear Box Condition | OIL LEAK & JERKING | حالة الجير النظرى |
| 01.C Gear Box Mount | MOUNT BUSH CRACKED | كرسي الجير |
| 02 Interior Condition | | الحاله الداخليه |
| 02.A AC Condition | OK | المكيف |
| 02.B Roof Ceiling | LOOSE | بطانه السقف |
| 02.C Other | COVER LOOSE . GEAR LEVER SHIFT LOCK MISSING | اخرى |
| 03 Lights | | الاضاءة |
| 03.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |
| 03.B Fog light | LEFT SIDE NOT WORKING | كشاف الضباب |
| 03.C Brake Light | NOT WORKING | نور الفرامل |
| 03.D Tail Light | REAR LEFT SIDE PARK LIGHT NOT WORKING | الانارة |
| 03.E Head Light | PORTION FADED | الاضاءة الرئيسية |
| 04 Tires and Rims Condition | | الاطارات |
| 04.A Rear Tyre | BOTH SIDE 2017 CRACKED , EXPIRED | الاطار الخلفي |

| DEFECT | REMARKS | |
|------------------------------|---|---------------------|
| 04.B Front Tyre | BOTH SIDE 2019 MINOR CRACKED | الاطار الامامي |
| 05 Steering Condition | | المقود |
| 05.A Tie Rod End | BOOT CUT | مؤخرة الرودادات |
| 05.B Steering Boot | BOOT CUT | ربلة المقود |
| 05.C Axle | FRONT AXLE BOOT CUT | اكسلات |
| 06 Body | | جسم المركبة |
| 06.A Bonnet | REFITTED | غطاء المحرك |
| 06.B Floor | UNDER FLOOR CHASSIS TOO MUDDYCHECKED VISIBLE AREA / LEFT SIDE RUNNING BOARD DENT | الارضية |
| 06.C Paint | BODY REPAINTED EXCEPT ROOF& PORTION REPAIRED , MINOR DENT, SCRATCHES ,PORTION FADED,PAINT PORTION DAMAGED | الصبغ |
| 07 Engine Condition | | المحرك |
| 07.A Mount | MOUNT BUSH CRACKED | كرسي |
| 07.B Visual Engine Condition | OIL LEAK | حالة المحرك النظري |
| 08 Suspension System | | ممتص الصدمات |
| 08.A Arms | FRONT LOWER ARM BUSH CRACKED | ازرع |
| 08.B Ball Joint | BOOT CUT | مفصل كروي |
| 08.C Other | STABILIZER LINK BOOT CUT | اخرى |
| 09 Chassis Condition | | الشاسي |
| 09.A Chassis | CHECKED VISIBLE AREA OK | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.