





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20768807	Plate Category	: PRIVATE
Transaction Date	: 25 AUG 2020 15:15:46	Plate Number	: 111859 EA
Queue Number	: 211338	Import Doc. Ref.	:
Chassis Number	: 1GKFK13067J111859	Manufacturer/Model	: GMC/YUKON
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.02 - Steering Mounting, Tight, Crack		مثبت عجلة القيادة
02.10 - Ties Rods, Bushes, Center Link, Left And Right		ربلات ذراع التوجيه
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
02.17 - Gear Box Mounting		كراسي ناقل الحركة
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصيغ
05.06 - Roof		السقف
05.08 - Chassis (Frame)		الشاصية
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرآيا الجانبية
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20768807	Plate Category	: PRIVATE
Transaction Date	: 25 AUG 2020 15:15:46	Plate Number	: 111859 EA
Queue Number	: 211338	Import Doc. Ref.	:
Chassis Number	: 1GKFK13067J111859	Manufacturer/Model	: GMC/YUKON
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling	NOT COOLING	عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	TPMS/ STABILITRAC/ ENGINE MALFUNCTION/ SRS AIRBAG LIGHTS ON	عطل في لوحة التحكم الإلكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صنيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئول عن العيوب الخفية</p>		

Test Certificate

FAILED



Plate Details :	--
Chassis No :	1GKFK13067J111859
Vehicle Make :	GMC
Vehicle Model :	YUKON
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	316261 Kms.
Origin : United States	Model Year : 2007
Gear Type : --	Engine Size : 6600 CC
Engine No : NIL	Horse Power : 320
Axles No : 2	Cylinders : 8
No Of Doors : 4	No Of Seats : 9
G. V. W. : 3629 Kgs.	Empty Weight : 2507 Kgs.

Certificate Number :	5-TAS-2020-12351255
Inspection Date :	16-08-2020
Certificate Print Date :	16-08-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	12 min 6 sec
Appointment Ref Number :	--
Start Time : 12:39	End Time : 12:51
Lane : 01	Token No. : 171
Attempt : 1	Prints No : 2

Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 8 %	Parking brake imbalance between LHS and RHS 5 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 18 PPM VOL			

Inspection Findings

Defects

Defects	Issue	Severity
Tire CHANGE ALL TIRES DRY AND CRACK	Cracked	Major

Discrepancies

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	6600	5300	
Seats Incorrect Number of Seats	9	7	

Inspection Remarks: FRONT BUMPER AND RIGHT FENDER REPAIRED//UNDERNEATH MINOR RUSTY