CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2944996
Transaction Date	06 Nov 2026, 16:18:43
Site Name	840 - Emirates Auctions
Transaction Number	40679287 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JM7GJ4S35F*******
Specification	GCC Specification
Make	Mazda
Model	6
Model Year	2015
Color	Blue
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE FENDER ,REAR BOTH SIDE QUARTER PANEL REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	LEFT SIDE BOTH DOORS REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED.	غطاء المحرك
01.H Trunk	NOT OPEN ,REPAINTED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident	LEFT SIDE RUNNING BOARD DAMAGED .	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY ,PORTION DENT ,CHECKED ONLY VISIBLE AREA .	الشاسيه
02.B Other	NEED TO REMOVE FENDER UNDER COVER FOR RECHECK .	اخري
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED.	كرسي

Condition	Remarks	الحالة
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY PORTION LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CUT	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR CONDITION RUSTY SIGN OF WATER FLOODED.	اخري
11.B Power Window Switch And Glass	RIGHT SIDE WINDOW GLASS OPEN	مفتاح النافذه و الزجاج
11.C Audio	SCREEN FADED.	صوتيات
11.D Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**