



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **18 Nov 2022, 09:52:38**  
 Transaction Number **25763005 (CC10006)** Queue Number **625727**



Chassis Number **JTJHY00W8K4305402**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Lexus**  
 Model **LX 570**  
 Model Year **2019**  
 Color **White**  
 Mileage **112779 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **8**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Visual Engine Condition	OK	حالة المحرك النظري
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	OK	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Paint	BODY MINOR DENT ,SCRATCHES	الصبغ
05.B Rusty	UNDER BODY PARTS, SUSPENTION ,CHASSIS FRAME GETTING MINOR RUSTY	صدأ
<b>06 Chassis Condition</b>		<b>الشاصي</b>

## DEFECT

## REMARKS

06.A Chassis

OK

الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.