CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966522
Transaction Date	10 Nov 2026, 11:53:32
Site Name	840 - Emirates Auctions
Transaction Number	36045110 (CC10009) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NY3D*******
Specification	Imported
Make	Nissan
Model	Patrol
Model Year	2013
Color	Black
Mileage	110266 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES,BODY KIT MODIFIED,PORTION RUSTY	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS CHASSIS SUSPENSION GETTING RUSTY	صدأ
01.E Floor	FLOOR COMPLETELY THICK RUST PROOFED, MUDDY DIRTY, NOT VISIBLE	الارضية
01.F Bumper	MISALIGN PORTION CRACK,REFLECTOR FADED SIDES PARKING SENSOR MISSING	دعامية
01.G Roof	ROOF,ROOF RAIL REPAIRED	السقف
01.H Bonnet	REFITTED,STAY SHOCK NOT WORKING	غطاء المحرك
01.I Pillars	DOOR PILLARS ROCKER PANEL REPAIRED,INNER COVER PORTION LOOSE	القوائم
01.J Trunk	REFITTED & REAR SWITCH NOT WORKING,INNER HANDLE SWITCH MISSING	صندوق
01.K Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.L Sign of side accident		وجود مؤشر لحادث في الجانب
01.M Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS GETTING RUSTY PORTION MINOR DENT,OK	الشاسيه
02.B Other	STEAM WASH FOR RECHECK PROPERLY	اخري
02.C Chassis Number	MANUFACTUR STICKER MISSING, CLEAN FRAME NUMBER	رقم القاعدة

Condition	Remarks	الحالة
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	OIL LEAK REFITTEDSHAKING GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT LOOSE COVER PORTION CRACK ADJUSTMENT SWITCH PORTION DAMAGED LOOSE SIDE COVER LOOSE & MIDDLE SEATS SIDE COVER PORTION DAMAGED	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Catalytic Converter	SOPT CUT RWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACK WORN OUT	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2024 CRACK WORN OUT,RIGHT 2026	الاطار الخلفي
07.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07.D Spare Tire &Tools	TOOLS MISSING	الاطار الاحتياطي و العدة
08 Lights		الاضاءة
08.A Head Light	PORTION DAMAGED REPAIRED	الاضاءة الرئيسية
08.B Tail Light	LEFT SIDE PORTION CRACKED FADED	الضوء الخلفي
08.C Indicator & Hazard light	LEFT SIDE MIRROR INDICATOR NOT WORKING	الاشارات
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	FRONT LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CUT	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
10.B Steering Boot	BOOT CUT	ربلة المقود
10.C Tie Rod End	BOOT CUT	مؤخرة الرودات
10.D Axle	RIGHT SIDE BOOT CUT	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR MODIFIED PARTS,WATER FLOODED REFITTED,CENTER CONSOLE BOX SIDE PANEL PORTION LOOSE	اخري
11.B Mirror	ADJUSTMENT NOT WORKING,LEFT SIDE COVER FADED	المرايا
11.C AC Condition	OK,GRILL PORTION LOOSE	المكيف
11.D Roof Light	NOT WORKING PROPERLY,PANEL LOOSE	أنارة السقف
11.E Power Window Switch And Glass	FRONT RIGHT SIDE GLASS CRACKED SWITCH LOOSE NOT WORKING PROPERLY & REAR RIGHT NOT WORKING	مفتاح النافذه و الزجاج

Condition	Remarks	الحالة
11.F Dash Board	PORTION WORN OUT	لوحة القياده
11.G Roof Ceiling	PORTION LOOSE	بطانه السقف
11.H Odometer reading	CLUSTER COVER MINOR SCRATCHES WORN OUT	قراءة عداد المسافات
11.I Door Panel	PORTION WORN OUT DAMAGED	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.K Sunroof	CURTAIN HANDLE MISSING	فتحت سقف
11.L Gear Shifting Lever	KNOB WORN OUT DUST COVER LOOSE,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
12 Battery Condition		حالة البطارية
12.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**