CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2981803
Transaction Date	13 Nov 2026, 15:07:39
Site Name	840 - Emirates Auctions
Transaction Number	33238630 (CC10026) (CC10026)



Vehicle Details

Chassis Number	KMHE241G7H*******
Specification	GCC Specification
Make	Hyundai
Model	Sonata
Model Year	2017
Color	Grey
Mileage	121289 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	BOTH SIDE REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,DENTS SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTSGETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PARTS PORTION COVER, PORTION DENT	الارضية
01.F Bumper	MISALIGN , REAR BUMPER BADLY DAMAGE	دعامية
01.G Bonnet	REFITTED , RPAINTED PORTION REPAIRED ,STAY SHOCK WEAK , NOT WORKING	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION RUSTY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK , ABNORMAL SOUND	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OILWET	الحالة النظريه للجير

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENT SCATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Steering Condition		المقود
08.A Steering Box	MINOR OIL LEAK	جهاز المقود
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	OK	المكيف
09.C Roof Light	RIGHT SIDE NOT WORKING	أنارة السقف
09.D Dash Board	BADLY CRACK	لوحة القياده
09.E Roof Ceiling	FABRIC PORTION LOOSE	بطانه السقف
09.F Sun Visor	LEFT SIDE GLASS LIGHT NOT WORKING	حاجب الشمس
09.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.H Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	PORTION WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**