



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	31 Jul 2022, 18:15:12
Transaction Number	16779358 (CC10006)	Queue Number	312309



Chassis Number	JTHBL46F905034815
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LS 460
Model Year	2007
Color	Silver
Mileage	143025 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	Japan Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE , REAR RIGHT SIDE REPAIRED, REPAINTED	مدكار
01.B Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
01.C Doors	RIGHT SIDE BOTH PORTION REPAIRED , REPAINTED	أبواب
01.D Pillars	RIGHT SIDE OUTER PILLAR PORTION REPAIRED & REPAINTED	القوائم
01.E Bumper	MISALIGN	دعامية
01.F Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.G Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.H Floor	UNDER BODY COVERD & ONLY VISABLE AREA CHECK	الارضية
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
02 Lights		الاضاءة
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي

DEFECT	REMARKS	
04 Suspension System		ممتص الصدمات
04.A Ball Joint	BOOT CUT	مفصل كروي
04.B Arms	LOWER ARM BUSHES CRACKED	ازرع
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05.B Axle	BOOT CRACKED	اكسلات
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظرى
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Engine Condition		المحرك
07.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
07.B Smoke	MINOR BLACK SMOKE	دخان
08 Interior Condition		الحاله الداخليه
08.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.B AC Condition	OK	المكيف
08.C Dash Board	WORN OUT	لوحة القيادة
09 Chassis Condition		الشاسي
09.A Chassis	CHASSIS VISABLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.