



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 May 2022, 12:39:31</b>
Transaction Number	<b>85708610 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTMHX09JXD5019657</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Land Cruiser</b>
Model Year	<b>2013</b>
Color	<b>Silver</b>
Mileage	<b>536572 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Lights</b>		<b>الاضاءة</b>
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.B Head Light	RIGHT SIDE LENS FADED	الاضاءة الرئيسية
01.C Indicator & Hazard light	FRONT LEFT SIDE INDICATOR NOT WORKING	الاشارات
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A AC Condition	OK	المكيف
02.B Mirror	BOTH SIDE FOLDING NOT WORKING , LOOSE & RIGHT SIDE ADJUSTMENT NOT WORKING & VIEW MIRROR MINOR LOOSE	المرايا
02.C Other	CENTER CONSOLE BOX LOCK DAMAGED	اخرى
02.D Steering Wheel and control buttons	MINOR WORN OUT	عجلة القيادة وازرار التحكم
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Fenders	FRONT LEFT SIDE REFITTED	مدكار
03.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
03.C Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES	الصبغ
03.D Doors	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب

DEFECT	REMARKS	
03.E Other	FRONT FENDER FRAME , RADIATOR SUPPORT REPAIRED	اخرى
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2020 & MINOR CRACKED	الاطار الامامي
05.B Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
05.C Rear Tyre	BOTH SIDE 2020 & MINOR CRACKED	الاطار الخلفي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Other	STABLIZER LINK BOOT CUT	اخرى
06.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
<b>07 Brake Condition</b>		<b>الفرامل</b>
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Hand Brake	MINOR WEAK	فرامل اليد
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Steering Oil	OIL LEAK	زيت المقود
<b>10 Transmission Condition</b>		<b>الجير</b>
10.A Road Test	NOT CHECK	فحص علي الطريق
10.B Visual Gear Box Condition	SIGN OF LEAK & REFITTED	حالة الجير النظرى
<b>11 Chassis Condition</b>		<b>الشاسي</b>
11.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.