

Queue Number 2783720

Transaction Date 21 Sep 2026, 13:49:08

Site Name
840 - Emirates AuctionsTransaction Number
80696284 (CC10010) (CC10010)

Vehicle Details

Chassis Number	MA3JB7D11N*****
Specification	GCC Specification
Make	Suzuki
Model	Jimny
Model Year	2022
Color	--
Mileage	146534 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE OUTER FENDER SKIRT PORTION FADED SCARTCHES	مدكار
01.B Paint	MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Bumper	MISALIGN , PORTION DENTS	دعامية
01.E Windshield	FRONT CHANGED.	زجاج
01.F Vehicle Color	GREEN/BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME COMPLETE THICK RUSTPROOFED ,PORTION SPOT RUSTY/OK.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENT PARTS GETTING RUSTY.	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FABRIC DIRTY	حالة المقاعد
---------------------	--------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL LEAK ,COMPONENT PARTS GETTING RUSTY.	الحالة النظرية للجير
--------------------------------	--	----------------------

06 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	WIFER ARM CONTROL STICK PORTION GETTING FADED	اخرى
08 Lights		الاضاءة
08.A Fog light	LENS FADED	كشاف الضباب
09 Brake Condition		الفرامل
09.A Break Pads	WEAR.	سفايف الرامل
09.B Disc&Drum	RUSTY.	دسك و طنابير الفرامل
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX PANEL LOOSE , INTERIOR PARTS GETTING RUSTY/SIGN OF FLOODED.	اخرى
10.B AC Condition	OK	المكيف
10.C Floor Matting	DIRTY	فرش الأرضيه
10.D Dash Board	WORN OUT	لوحة القيادة
10.E Roof Ceiling	FABRIC PORTION LOOSE	بطانه السقف
10.F Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carcheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carcheck.ae