



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2022, 18:15:25
Transaction Number	25053636 (CC10006)	Queue Number	312309



Chassis Number	3N1BC1A66CK258273
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Tiida
Model Year	2012
Color	White
Mileage	296026 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Tail Light	REAR BOTH SIDE COVER CRACKED	الانارة
01.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.C Head Light	OK	الاضاءة الرئيسية
01.D Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
02 Body		جسم المركبة
02.A Trunk	REPAIRED & REPAINTED	صندوق
02.B Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
02.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
02.D Fenders	PORTION REPAIRED & REPAINTED	مدكار
02.E Bumper	REPAIRED ,REPAINTED & MISALIGN	دعامية
02.F Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
02.G Other	REAR BACK PANEL, QUATER PANEL , SPARE WHEEL HOUSING REPAIRED & OPEN DETACHED	اخرى
03 Engine Condition		المحرك
03.A Engine Condition	OK	حالة المحرك

DEFECT	REMARKS	
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OK	الجير
05 Seats Condition		المقاعد
05.A Seat Condition	OK	حالة المقاعد
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
07 Tires and Rims Condition		الاطارات
07.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
08 Interior Condition		الحاله الداخليه
08.A Mirror	OK	المرايا
08.B AC Condition	OK	المكيف
08.C Dash Board	PORTION CRACKED	لوحة القيادة
08.D Other	HRON NOT WORKING	اخرى
09 Chassis Condition		الشاصي
09.A Chassis Extension	REAR LEFT SIDE END REPAIRED	تمديدات الشاسي
09.B Chassis	OK	الشاسيه
10 Steering Condition		المقود
10.A Axel	AXL CASE LEAKING	اكسلات
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.