





### Test Certificate

Site Number	: 752-AL AWEER	Plate Code	: 0
Transaction Number	: 27094670	Plate Category	: PRIVATE
Transaction Date	: 16 JUN 2021 13:37:08	Plate Number	: 004700 COM
Queue Number	: 888	Import Doc. Ref.	:
Chassis Number	: MMBJNKA50ED004700	Manufacturer/Model	: MITSUBISHI/L200
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 216482

#### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية
		HEAD LIGHT LENS FADED
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
		STEERING BOOT CRACK & LEAK
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
		FRONT LOWER ARM BALL JOINT WORN OUT
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRE DOT 2018 / 2019 / DRY CRACK
05 Body		الهيكل
05.02 - Paint		الصبغ
		BODY MINOR SCRATCH & DENT
05.08 - Chassis (Frame)		الشاصية
		CHASSIS RUSTY
05.12 - Side Safety Frame		الواقيات الجانبية
		FRONT CROSS MEMBER DENT
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
		WIPER BLADE WORN OUT
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		INTERIOR PARTLY WORN OUT
06.14 - Transmission Condition		حالة ناقل الحركة
		GEAR OIL LEAK
06.15 - Clutch		الكلتش
		CLUTCH SLIP ( ROAD TEST NOT DONE )
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		ENGINE OIL LEAK / DIP STICK BROKEN / VALVE COVER RUSTY
09 Auction		الفحص الكامل



### Test Certificate

Site Number	: 752-AL AWEER	Plate Code	: 0
Transaction Number	: 27094670	Plate Category	: PRIVATE
Transaction Date	: 16 JUN 2021 13:37:08	Plate Number	: 004700 COM
Queue Number	: 888	Import Doc. Ref.	:
Chassis Number	: MMBJNKA50ED004700	Manufacturer/Model	: MITSUBISHI/L200
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION	Mileage	: 216482

Statement of Vehicle Condition

09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية</p>		

# Test Certificate



Vehicle  
Registration



✓ PASS

Transfer Certificate :	64657566
Chassis No :	MMBJNKA50ED004700
Vehicle Make :	MITSUBISHI
Vehicle Model :	L200
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	216482 Kms.
Origin :	Thailand
Model Year :	2014
Gear Type :	--
Engine Size :	3000 CC
Engine No :	4G64AU0639
Horse Power :	--
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	6
G. V. W. :	Empty Weight : 1500 Kgs. 2500 Kgs.

Certificate Number :	5-TAS-2021-14426648
Inspection Date :	17-06-2021
Certificate Print Date :	17-06-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	16 min 21 sec
Appointment Ref Number :	--
Start Time :	10:08
End Time :	10:24
Lane :	03
Token No. :	109
Attempt :	1
Prints No :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

14421 KM	1484 L	2405 AED	3.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 12 %	Service brake imbalance on rear axle 6 %	Parking brake imbalance between LHS and RHS 18 %	Vehicle on Petrol CO Reading 0.53 %
---	---	---	--

## Vehicle on Petrol HC Reading

112 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3000	2500	

## Inspection Remarks:

CHASSIS&FLOOR MINOR RUSTY/ THICK RUST PROOF/ MINOR GEAR&STEERING BOX OIL LEAK/FRONT BULKHEAD&BUMPER REPAIRED

## Payment Details

Inspection Performed by 62439	Payment Method Cash	Transaction Number 14426648	Service Fees AED 170 Collected on 17/06/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Abdul Rasheed Hussain

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

