



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Oct 2021, 17:59:32
Transaction Number	72497594 (CC10006)	Queue Number	312309



Chassis Number	SALLSAA346A935717
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2006
Color	Red
Mileage	125861 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	European Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	TOTALLY REPAINTED , PORTION REPAIRED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Bumper	REPAINTED	دعامية
01.E Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.F Roof	REPAINTED	السقف
01.G Rusty	UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY	صدأ
01.H Floor	UNDER FLOOR PORTION COVER	الارضية
02 Chassis Condition		الشاصي
02.A Chassis	VISABLE AREA OK	الشاسيه
02.B Other	VIN NUMBER ON DOOR MISSING	اخرى
03 Engine Condition		المحرك
03.A Other	SIGN OF LEAK	اخرى
04 Seats Condition		المقاعد

DEFECT	REMARKS	
04.A Other	OK	اخرى
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH 2019	الاطار الامامي
05.B Rear Tyre	BOTH 2019	الاطار الخلفي
06 Wipers and Arms		المساحات
06.A Other	OK	اخرى
07 Lights		الاضاءة
07.A Head Light	HEAD LIGHT LENS FADED & HIGH BEAM NOT WORKING	الاضاءة الرئيسية
07.B Other	OK	اخرى
07.C Indicator	REAR RIGHT SIDE NOT WORKING	الاشارات
07.D Tail Light	REAR RIGHT SIDE COVER DAMAGED	الانارة
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
09.B Shock Absorber	OIL LEAK	ممتص الصدمات
10 Transmission Condition		الجير
10.A Gear Box	OIL LEAK	الجير
10.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
11 Steering Condition		المقود
11.A Steering Box	OIL LEAK	جهاز المقود
12 Interior Condition		الاجزاء الداخلية
12.A Other	INNER HANDLE DAMAGED	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.