



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 Sep 2022, 18:00:00
Transaction Number	36520869 (CC10006)	Queue Number	593661



Chassis Number	WDB1400571A119204
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	S 600
Model Year	1993
Color	White
Mileage	144600 Km
Fuel Type	Petrol
No. Of Cylinders	12
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.B Bonnet	PORTION REPAIRED,REPAINTED & REFITTED,ENGINE COMPARTMENT WIRING LOOSR ,COVER MISSING.	غطاء المحرك
01.C Pillars	LEFT SIDE ROOF RAIL REPAINTED	القوائم
01.D Rusty	AVOID UNDER BODY PARTS GETTING RUSTY .	صدأ
01.E Other	FRONT BUMPER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,FENDER FRAME ,CROSS MEMBER REPAIRED.	اخرى
01.F Floor	BACK PANEL ,UNDER FLOOR PORTION GETTING RUSTY .	الارضية
01.G Sign of front accident		وجود مؤشر لحادث في المقدمة
01.H Doors	CENTER LOCK SYSTEM NOT WORK PROPERLY	أبواب
01.I Fenders	FRONT BOTH SIDE , REAR LEFT SIDE PORTION REPAIRED REPAINTED & REFITTED	مدكار
01.J Trunk	REPAINTED	صندوق
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK	المكيف
02.B Sun Visor	BOTH SIDE MIRROR COVER MISSING	حاجب الشمس
02.C Power Window Switch	REAR RIGHT SIDE NOT WORKING PROPERLY	مفتاح النافذة

DEFECT	REMARKS	
02.D Sunroof	NOT WORKING	فتحت سقف
03 Lights		الاضاءة
03.A Head Light	RIGHT SIDE NOT WORK	الاضاءة الرئيسية
03.B Other	RIGHT ROOF LIGHT NOT WORK.	اخرى
04 Chassis Condition		الشاصي
04.A Chassis	FRONT BOTH SIDE CHASSIS END ,REPAIRED.	الشاسيه
05 Suspension System		ممتص الصدمات
05.A Suspension Subframe	MINOR DENT .	
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
07 Engine Condition		المحرك
07.A Visual Engine Condition	REFITTED OIL LEAK.	حالة المحرك النظرى
08 Transmission Condition		الجير
08.A Propeller Shaft	MOUNT BUSHES CUT	ناقل الحركة
08.B Road Test	NOT CHECK	فحص علي الطريق
08.C Visual Gear Box Condition	JERKING &REFITTED MINOR OIL WET.	حالة الجير النظرى
09 Exhaust System		نظام العادم
09.A Modification	REWELDED.	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	Y 41833 Dubai Private
Chassis No :	WDB1400571A119204
Vehicle Make :	MERCEDES
Vehicle Model :	S600
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	144600 Kms.
Origin : Germany	Model Year : 1993
Gear Type : Automatic	Engine Size : 6000 CC
Engine No : NIL	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 12
Doors :	No Of Seats : 5
G. V. W. : 2250 Kgs.	Empty 1800 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17741521		
Inspection Date :	29-09-2022		
Certificate Print Date :	29-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	13 min 8 sec		
Appointment Ref Number :	--		
Start Time :	10:38	End Time :	10:51
Lane :	01	Token No. :	126
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	12 %	37 %	2.44 %
Vehicle on Petrol HC Reading			
275 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	5	4	
Incorrect information about GCC specifications with No Document	No	Yes	

Inspection Remarks: MINOR ENGINE&GEAR OIL LEAK/ MINOR BODY SCRATCHES&DENT

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	VTP Credit Account	17741521	AED 170 Collected on 29/09/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

