



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **24 Jan 2023, 16:23:09**
 Transaction Number **53601702 (CC10010)** Queue Number **660731**



Chassis Number **JN1FN61C72W011684**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Sunny**
 Model Year **2002**
 Color **Gold**
 Mileage **19783 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	EXPIRED,DAMAGED	الاطار الامامي
01.B Rear Tyre	EXPIRED,DAMAGED	الاطار الخلفي
02 Suspension System		ممتص الصدمات
02.A Ball Joint	BOOT CUT	مفصل كروي
02.B Shock Absorber	LEAK	ممتص الصدمات
02.C Arms	LOWER ARM BUSH CUT	ازرع
02.D Other	STABILIZER LINK BOOT CUT	اخرى
03 Body		جسم المركبة
03.A Sign of back accident		وجود مؤشر لحادث في الخلف
03.B Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT & REAR BACK PANEL,QUATER PANEL,SPARE WHEEL HOUSING,COMPARTMENT REPAIRED	اخرى
03.C Sign of front accident		وجود مؤشر لحادث في المقدمة
03.D Fenders	FRONT REFITTED	مدكار
03.E Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES PORTION FADED,PORTION RUSTY	الصبغ
03.F Bonnet	REFITTED	غطاء المحرك

DEFECT	REMARKS	
03.G Rusty	UNDER BODY PARTS SUSPENSION RUSTY	صدأ
03.H Bumper	MISALIGN,PORTION DAMAGED	دعامية
03.I Floor	PORTION DENT,RUSTY WEAK HOLE	الارضية
04 Interior Condition		الحاله الداخليه
04.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
04.B Other	CENTER CONSOLE BOX DAMAGED	اخرى
04.C AC Condition	NOT WORKING	المكيف
04.D Dash Board	PORTION DAMAGED,CONSOLE BOX DAMAGED	لوحة القيادة
04.E Power Window Switch	NOT WORKING PROPERLY	مفتاح النافذه
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Gear Box Mount	CRACKED	كرسي الجير
05.C Visual Gear Box Condition	REFITTED	حالة الجير النظرى
06 Steering Condition		المقود
06.A Steering Oil	OIL LEAK	زيت المقود
06.B Axle	BOOT CUT	اكسلات
06.C Steering Boot	BOOT CUT	ربلة المقود
06.D Tie Rod End	BOOT CUT	مؤخرة الرودادت
07 Seats Condition		المقاعد
07.A Seat Condition	PORTION DAMAGED	حالة المقاعد
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسيه
09 Engine Condition		المحرك
09.A Visual Engine Condition	OIL LEAK REFITTED,MISFIRING	حالة المحرك النظرى
09.B Smoke	WHITE SMOKE	دخان
10 Chassis Condition		الشاصي
10.A Chassis	FRONT LEFT SIDE CHASSIS END & REAR BOTH SIDE CHASSIS EXTENSION REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

fitness for registration.