



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **26 Oct 2024, 12:57:17**  
 Transaction Number **73707819 (CC10010) (CC10010)** Queue Number **1100241**



Chassis Number **JMYLRV95WCJ703649**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Mitsubishi**  
 Model **Pajero**  
 Model Year **2012**  
 Color **Brown**  
 Mileage **N/A NA**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

| DEFECT                           | REMARKS                                                                                            |                       |
|----------------------------------|----------------------------------------------------------------------------------------------------|-----------------------|
| <b>01 Body</b>                   |                                                                                                    | <b>جسم المركبة</b>    |
| 01.A Paint                       | BODY PORTION REPAINTED , PORTION REPAIRED,, DENTS, SCRATCHES ON BODY, PORTION FADED, PORTION RUSTY | الصبغ                 |
| 01.B Floor                       | UNDER BODY PARTS, SUSPENSION, FLOOR, CHASSIS NOT CHECK                                             | الارضية               |
| 01.C Bumper                      | MISALIGN , PORTION DAMAGED                                                                         | دعامية                |
| 01.D Windshield                  | CRACKED                                                                                            | زجاج                  |
| 01.E Other                       | VISUAL TEST ONLY                                                                                   | اخرى                  |
| <b>02 Chassis Condition</b>      |                                                                                                    | <b>الشاسي</b>         |
| 02.A Chassis                     | NOT CHECK                                                                                          | الشاسيه               |
| <b>03 Engine Condition</b>       |                                                                                                    | <b>المحرك</b>         |
| 03.A Engine Visual Condition     | ENGINE NOT START , ALL SYSTEM NOT CHECK                                                            | الحالة النظرية للمحرك |
| <b>04 Transmission Condition</b> |                                                                                                    | <b>الجير</b>          |
| 04.A Gear Box Visual Condition   | NOT CHECK                                                                                          | الحالة النظرية للجير  |
| <b>05 Lights</b>                 |                                                                                                    | <b>الاضاءة</b>        |
| 05.A Head Light                  | LENS FADED , ALL LIGHTS NOT CHECK                                                                  | الاضاءة الرئيسية      |

| DEFECT                                  | REMARKS                    |                            |
|-----------------------------------------|----------------------------|----------------------------|
| 05.B Tail Light                         | PORTION CRACKED.           | الانارة                    |
| <b>06 Interior Condition</b>            |                            | <b>الحالة الداخليه</b>     |
| 06.A Other                              | INTERIOR CONDITION DIRTY . | اخرى                       |
| 06.B AC Condition                       | NOT CHECKED .              | المكيف                     |
| 06.C Dash Board                         | PORTION CRACK .            | لوحة القيادة               |
| 06.D Odometer reading                   | NOT CHECKED .              | قراءة عداد المسافات        |
| 06.E Door Panel                         | PORTION LOOSE .            | لوحة بطانة الباب           |
| 06.F Steering Wheel and control buttons | WORN OUT .                 | عجلة القيادة وازرار التحكم |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.
- For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.
- للشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)